

**Michael F. Del Casino**  
Regulatory Division Manager

Suite 1000  
1120 20th Street, N.W.  
Washington, DC 20036  
202 457-2023  
FAX 202 457-2165

August 17, 2000

00-109

Mr. Dale Hatfield  
Chief, Office of Engineering and Technology  
Federal Communications Commission  
2000 M Street NW, Suite 480  
Washington, DC 20554

Dear Mr. Hatfield:

As required by Part 63.100(a) of the Commissions Rules, AT&T hereby files its Final Service Disruption Report for an AT&T network outage.

**1. DATE / INCIDENT LOCATION TIME:**

July 18, 2000 05:52 AM EDT

**2. GEOGRAPHICAL AREA AFFECTED:**

Albuquerque, NM

**3. CUSTOMERS AFFECTED (APPROXIMATELY):**

34,274 (based on blocked calls)

**4. TYPES OF SERVICES AFFECTED:**

Intertoll and Toll Access

**5. DURATION OF OUTAGE:**

2 hours 23 minutes

**6. BLOCKED CALLS:**

102,822

## **7A. CAUSE OF INCIDENT:**

During a maintenance activity, an AT&T technician removed power from the Albuquerque, NM 4ESS in order to place a diagnostic fault insertion board in the Time Slot Interchange (TSI). The technician removed the circuit pack to place the insertion board, but when he replaced the pack in the slot he inserted the wrong type, which caused the TSI to duplex fail. As power was restored to the switch, loss of communication occurred to the peripheral units, resulting in the service disruption.

## **7B. EQUIPMENT NAME / TYPE:**

4ESS

## **7C. PART OF NETWORK:**

Albuquerque, NM

## **8. RESTORATION METHODS:**

Manual attempts were made to recover the switch and when power was removed for the second time, it was discovered that circuit packs were in the wrong slots. Communication to the peripheral units was restored when the circuit packs were placed in the proper slot locations.

## **9. STEPS TO PREVENT REOCCURRENCE:**

AT&T reconfirmed with technicians, the critical step to verify slot locations and corresponding circuit pack types before allowing insertions into the frames.

## **10. APPLICABLE BEST PRACTICES:**

AT&T has reviewed the Network Reliability: A Report to the Nation, June 1993 and has evaluated all best practices in SECTION C – SOFTWARE AND SWITCHING SYSTEM RELIABILITY: CAUSE, CURE, OR BOTH? The following practices have been identified as the most applicable to this incident, and will be explored as potential safety fixes in order to prevent future service disruptions of this nature.

Section 5.1.3.1 – Procedural error should be replaced with an additional layer of problem definition that would include but not be limited to:

- human factors: not clearly marked, equipment layout not consistent, machine to people communication ambiguous, etc.
- system action: allowed improper request, did not warn of severity of requested action, etc.

Section 5.1.3.6 – System Suppliers should enhance existing, or establish new, standards for system robustness to prevent switching systems from accepting or allowing service affecting activity without a positive confirmation. These robustness standards should be applied to software (e.g., input verification, flow control validation, undo, etc.), hardware (e.g., lighting, labeling, numbering, positioning, warning indication, etc.).

Sincerely,

A handwritten signature in black ink that reads "Mike Del Caseno". The signature is written in a cursive, flowing style with a large initial "M" and a stylized "D".

THIS FORM SHOULD BE SENT FOR THE FOLLOWING CIRCUMSTANCES:

B/C 90,000 - 149,999 3 days

B/C 150,000 &amp; greater 120 minutes

00-109

## AT&amp;T

## Initial Service Disruption Report

FAX TO: FCC WATCH OFFICE, WASHINGTON, DC

202-632-6975 Voice

202-418-2812 FAX

ALTERNATE FCC WATCH OFFICER

202-418-2813 FAX

1. Date/Time of Incident July 18, 2000 04:28 Mount. Daylight  
06:28 EDT
2. Geographic area affected ALBUQUERQUE, NM
3. Customers affected (est) 30K +
4. Types of service affected All Switch Services
5. Duration of outage 1 Hour 42 minutes
6. Blocked calls (est) 90K +
- 7a Cause of incident Under Investigation
- 7b Equipment name/types YES
- 7c Part of network affected ALBUQUERQUE, NM
8. Restoration methods used N/A
9. Steps to prevent recurrences N/A

AT&amp;T contact person:

Mike DelCasino

Telephone number:

202-457-2023

Date/Time of report:

July 18, 2000 09:55 EDT

called  
07-18-00  
10:11 AM/CP